

# CHANGELOG LABVIEW DRIVER FLEXCARD FAMILY

## LabVIEW Driver for FlexCard Family S6V1c-F

### Release Date:

January 14, 2010

### Description:

This is a bugfix release. The following items were fixed and/or added:

### Changes:

- Fixed: The loading of the ApiWrapper.dll creates an error in LabVIEW.
- Removed: LabVIEW Runtime Engine from Installer.

## LabVIEW Driver for FlexCard Family S6V1b-F

### Release Date:

January 13, 2010

### Description:

This is a bugfix release. The following items were fixed and/or added:

### Changes:

- Fixed: The VI "lv\_isValid.vi" was not included to the Installer of the version S6V1a-F.

## LabVIEW Driver for FlexCard Family S6V1a-F

### Release Date:

January 11, 2010

### Description:

This is a bugfix release. The following items were fixed and/or added:

### Changes:

- Fixed: Using the LabVIEW Driver within a LabVIEW Runtime environment no longer results in LabVIEW Error code 7. See also LabVIEW Driver FlexCard Family Documentation D1V1-F.